NTSB ID: DEN02FA070 Aircraft Registration Number: N30319

Occurrence Date: 07/08/2002 Most Critical Injury: None

Occurrence Type: Accident Investigated By: NTSB

Location/Time

Nearest City/Place	State	Zip Code	Local Time	Time Zone	
Englewood	со	80210	1938	MDT	
Airport Proximity: On Airport	Distance From	m Landing Facility:	0.5	Direction Fro	m Airport: 180

Aircraft Information Summary

All Clark Information Summary									
Aircraft Manufacturer	Model/Series	Type of Aircraft							
Boone	Rotorway 162-F	Helicopter							

Sightseeing Flight: No Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

HISTORY OF FLIGHT

On July 8, 2002, at 1938 mountain daylight time, a Boone Rotorway 162-F, N30319, amateur-built helicopter, was substantially damaged when it impacted terrain during aerial taxi at Centennial Airport (APA), Englewood, Colorado. Visual meteorological conditions prevailed at the time of the accident. The personal test flight was being conducted under the provisions of 14 CFR Part 91 without a flight plan. The pilot was not injured. The local flight originated at 1936.

The pilot reported that he was doing hover testing of his helicopter. He said the APA Air Traffic Control Tower had cleared him to aerial taxi from Hanger 25 to the compass rose. The pilot said to get to the compass rose, he determined he would have to fly west toward the Signature Aviation building and then turn south to fly behind the building (the west side of the building), and stay between the building and taxiway A, the north-south parallel taxiway to runway 35. The pilot said that as he passed behind the building, "I think I experienced a tailwind. The helicopter began losing power and lift. I set up to do a skidding landing. The helicopter skidded and tipped forward, caught the rotor on the ground."

In his written statement, the pilot added that he was flying at about 15 feet above the ground with a forward speed of 20 miles per hour. The pilot said that when he was south of the Signature Aviation building, he experienced significant tail winds and down drafts coming off of the hangar. The pilot said, "I experienced settling with power and did not have enough altitude to fly out of it."

PERSONNEL INFORMATION

The pilot held a private pilot certificate with single-engine land and helicopter ratings. The pilot reported having 465.2 total flying hours, and 63.6 hours in helicopters.

The pilot completed a flight review on November 11, 2001, in a Rotorway 162F helicopter.

The pilot held a second class medical certificate dated December 27, 2000, with limitations stating the holder shall possess glasses.

AIRCRAFT INFORMATION

The Federal Aviation Administration had certified the amateur-built helicopter for its 40-hour test flight period on June 23, 2002. The pilot reported that the helicopter had 2.5 hours total time.

METEOROLOGICAL INFORMATION

NTSB ID: DEN02FA070

Occurrence Date: 07/08/2002

Occurrence Type: Accident

Narrative (Continued)

At 1953, the Aviation Routine Weather Report for APA was few clouds at 9,000 feet, broken ceilings of 14,000 and 22,000 feet, visibility 10 statute miles, temperature 82 degrees Fahrenheit (F), Dew Point 53 degrees F, winds 360 degrees at 11 knots, and an altimeter setting of 30.29 inches of Mercury.

WRECKAGE AND IMPACT INFORMATION

The NTSB on-scene investigation began at 2030.

The helicopter wreckage was located on the south side of the airport approximately 150 feet west of a north-south segment of Peoria Street, the road proceeding from the south entrance of the airport.

The helicopter's main wreckage was resting in a field on its left side with the cabin oriented on a 180-degree magnetic heading. The helicopter's tail boom rested approximately 6 feet southeast of the cabin section. The tail boom was crushed inward from the top of the boom downward and severed 26 inches aft of the powerplant compartment. The tail rotor control cable was torn outward and unraveled. The core of the cable was wrapped around the tail boom and tail rotor gear box. The tail rotor gear box was broken out and resting just aft of the tail boom. One of the two tail rotor blades remained attached to the tail rotor hub and gear box. The other tail rotor blade was broken at the base and preceded the helicopter main wreckage resting 6 feet north of the engine compartment. The helicopter's horizontal stabilizer and vertical fin were bent aft and broken.

Several scrapes in the ground were observed preceding the helicopter main wreckage. One scrape was 8 feet long and 2 inches deep and described a wide arc. This scrape was located 5 feet northwest of the main wreckage. A second scrape was located 15 feet north-northwest of the helicopter main wreckage. It was 12 feet long and approximately 3 inches deep, and also described a wide arc.

Pieces of the Plexiglas bubble comprising the windscreen were broken out and resting forward of the helicopter's cabin section. The helicopter's cabin and engine compartment were intact. The smell of fuel was prevalent in the area around the fuselage. The bottoms of the front tips of both skids showed aft-running scrapes and scratches.

The lead main rotor blade (the blade extending over the cabin) was bent downward 20 degrees and twisted aft and downward beginning 26 inches outboard of the rotor head. The tip of the lead blade was torn open. Smears of dirt and chordwise scratches were observed along the entire span of the blade's leading edge.

The trailing main rotor blade (the blade extending aft) was bent downward and twisted counter-clockwise beginning at the rotor head and extending outward along the span of the blade. The trailing edge of the blade was bent and wrinkled.

Flight control continuity was confirmed. An examination of the engine and other helicopter systems revealed no anomalies.

ADDITIONAL INFORMATION

A party to the investigation was the FAA, Flight Standards District Office, Denver, Colorado.

The wreckage was released to the helicopter's owner.

NTSB ID: DEN02FA070

Occurrence Date: 07/08/2002

THE TOTAL ORT													
AVIATION		Occu	Occurrence Type: Accident										
Landing Facility/Approach Infor	mation												
Airport Name	Airport ID:	Airport Eleva	tion	Run	way Used	Runway Length			Runv	way Width			
Centennial Airport	APA	5880 Ft	. MSL										
Runway Surface Type: Unknown													
Runway Surface Condition: Rough; Vegetation													
Type Instrument Approach:													
VFR Approach/Landing:													
Aircraft Information													
Aircraft Manufacturer				/Series							Number		
Boone			Roto	rway 162-F					3279				
Airworthiness Certificate(s): Experimental (Special)													
Landing Gear Type: Skid													
Homebuilt Aircraft? Yes Nu	ımber of Seats:	2	Certifie	Certified Max Gross Wt. 1500 LBS						Number of Engines: 1			
				Engine Manufacturer: Model/Series: 162F						Rated Power: 150 HP			
- Aircraft Inspection Information													
Type of Last Inspection			Date of Last Inspection Time Sin			nce Last Inspection			Airfrar	me To	otal Time		
Conditional			06/2002	06/2002 2.5 Ho					ours 2.5 Hours				
- Emergency Locator Transmitter (ELT) Information												
ELT Installed? Yes	ELT Operate	ed? No		ELT Aided in Locating Accident Site? No									
Owner/Operator Information													
Registered Aircraft Owner			Street /	Address 6907 N.	Trailway	Circ	cle						
Douglas M. Boone			City	·							te	Zip Code 80134	
			Parker CO 80134 Street Address										
Operator of Aircraft			Same as Reg'd Aircraft Owner										
Same as Reg'd Aircraft Owner	City							Stat	te	Zip Code			
Operator Does Business As:			Op	perator Design	nator Co	ode:							
- Type of U.S. Certificate(s) Held: Nor	ie												
Air Carrier Operating Certificate(s):													
Operating Certificate:				Operator (Certificate:								
Regulation Flight Conducted Under: F	art 91: Genera	al Aviat	ion										
Type of Flight Operation Conducted: F	light Test												
		FACTU	JAL REPO	RT - AVIAT	ION							Page 2	

NTSB ID: DEN02FA070

Occurrence Date: 07/08/2002

ANTATION					0,700,2002									
	AVIATI	(PAN		Occurrence Type: Accident										
First Pilot Information														
Name		City				Sta	ate	Date of Birth	Age					
On File		On File			On File	49								
Sex: M	Seat Occupied:	er			Certificate Number: On File									
Certificate(s): Private														
Airplane Rating(s): Single-engine Land														
Rotorcraft/Glider/LTA: Helicopter														
Instrument	Rating(s): None	е												
Instructor Rating(s): None														
Type Rating	g/Endorsement fo	or Accident/In	cident Aircra	ft? No			Cu	urrent Bie	nnial Fligh	t Revie	w? 11/2	2001		
Medical Ce	rt.: Class 2	Medica	l Cert. Statu	s: Valid Med	dicalw/ wa	ivers/lim	١.		Date of	Last M	ledical E	xam: 12/2000)	
		<u> </u>				_			<u>'</u>					
- Flight Tim	ne Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night		Ins Actual	strument Simulate	ed	Rotorcraft	Glider	Lighter Than Air	
Total Time		465	7	396			21			5		63		
Pilot In Con	nmand(PIC)						_							
Instructor							4			_				
Last 90 Day	•	8	3	6								3		
Last 30 Day		8	3	6					_			3		
Last 24 Hou											1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
Seatbelt Us	sed? Yes	Shou	lder Harness	Used? Yes		T	Toxicology Performed? No Second Pilot? No							
Flight Pla	n/Itinerary													
Type of Flig	ht Plan Filed: No	one												
Departure F	Point					8	State	Ai	rport Identi	ifier	Departure Time		Time Zone	
Same as	Accident/Incide	nt Location						A	PA		1936		MDT	
Destination						5	State	Ai	Airport Identifier					
Local Flig	ht													
Type of Cle	earance: None													
Type of Air	space: Class	В												
Weather	Information													
Source of I		ord of briefi	ng											
Method of	Briefing: Unkno	wn									·			
	FACTUAL REPORT - AVIATION Page 3													

NTSB ID: DEN02FA070

Occurrence Date: 07/08/2002

Occurrence Type: Accident

	ETYBOP		Occurrenc	e Type:	Acciden	π								
Weather Information														
WOF ID	Observation Time	Time Zone	WOF Elevati	on	WOF Distance From Accident Site					Direction From	n Accident Site)		
APA	1953	MDT	5880 Ft.	. MSL				1 NM			360 Deg.	Mag.		
Sky/Lowes	st Cloud Condition: Few			9000 Ft. AGL					Condition of Light: Day					
Lowest Ce	illing: Broken		14000 Ft.	AGL	Visibi	ility:	10	SM	Altin	neter:	30.29	"Hg		
Temperatu	ure: 28 °C	Dew Point:	12 °C	°C Wind Direction: 360 Density Altitude: 8462								Ft.		
Wind Spee	ed: 11	Gusts:		Weather Condtions at Accident Site: Visual Conditions										
Visibility (R	RVR): Ft.	Visibility (R	VV)	SM	Intensit	y of Precip	oitation:							
Restriction	s to Visibility: None													
Type of Precipitation: None														
Accident	Information													
Aircraft Dar	mage: Substantial		Aircraft Fire	e: None				Aircraft Exp	losion	None				
Classificati	on: U.S. Registered/U	.S. Soil												
- Injury Su	mmary Matrix	Fatal Ser	rious Mino	or	None	TOTAL	T							
First Pil	lot				1		1							
Second	d Pilot						٦							
Studen	ut Pilot						7							
Flight II	nstructor						٦							
Check I	Pilot				-		7							
Flight E	Engineer						٦							
Cabin /	Attendants						٦							
Other C	Crew						7							
Passen	ngers						7							
- TOTAL ABOARD -														
Other G	Ground						7							
- GRANE	O TOTAL -				1		1							

NTSB ID: DEN02FA070

Occurrence Date: 07/08/2002

Occurrence Type: Accident

Administrative Information

Investigator-In-Charge (IIC)

David C. Bowling

Additional Persons Participating in This Accident/Incident Investigation:

Scott Christiansen Air Safety Inspector Federal Aviation Administration Denver, CO 80249